Version 221 Update

Updated Version 221 (6/19/23) firmware is now available on XR150/XR550 Series panels.

Panel Improvements

This update features a panel improvement where if the **Occupied Premises** option is set to **NO**, then the Exit Delay will not reset if a zone is opened during the Exit Delay countdown.

Obtaining the New Firmware

XR150/XR550 firmware updates are available, free of charge, on Dealer Admin (dealer.securecomwireless.com) or for download from DMP's Product Software Downloads.