Version 231 Update

Updated Version 231 (5/15/24) firmware is now available for XR150/XR550 Series panels.

Output Names Update

Wireless output names that are sent to 8860 Series Touchscreen Keypads via network communication will display properly on the keypad Attention List when the output goes into Low Battery, Trouble, or Missing.

Obtaining the New Firmware

Firmware updates are available, free of charge, on Dealer Admin (dealer.securecomwireless.com) or for download from DMP's Product Software Downloads.