Version 231 Date Code Update

Updated Version 231 (6/5/24) firmware is now available for XR150/XR550 Series panels.

Improvements

The XR150/XR550 Series panel processes door access requests with no delay when **Strike Time** in **Device Setup** is set to 0 (zero).

Programmed camera zones on the XV Gateway now correctly show up as **Faulted** when communication is lost.

Obtaining the New Firmware

XR150/XR550 Series firmware updates are available, free of charge, on Dealer Admin (dealer.securecomwireless.com) or for download from DMP's Product Software Downloads.