Version 252 Update

Updated Version 252 (7/17/25) firmware is now available for XT75 Control Panels.

Chime Improvement

Previously, when using the Carousel menu or pressing and holding 5 on a keypad to turn on the chime feature, the chime did not sound for wireless zones 550-599. If the chime was enabled through the user menu, it worked as intended. This update allows the chime to properly sound in all instances for those zones.

Obtaining the New Firmware

XT75 firmware updates are available, free of charge, on Dealer Admin (dealer.securecomwireless.com).