

## 1131 Software Update September 2008

### Version 100 Software Update

Effective September 2008, all 1131 Wireless Recessed Contacts are being manufactured with Version 100 (8/18/08) software. This version is an update from the Version 100 (4/15/08) software previously shipped and contains updated operation.

### Updated Operation

#### Battery Life Improved

The new Version 100 (8/18/08) software further improves the battery life of the 1131 contact. Most 1131 contacts manufactured since April of 2008 operate with the normal 5 year battery life expectancy. However, in a few cases, the processor operation could shorten battery life. This typically occurred when the contact was unable to communicate with the 1100 Series receiver. An indication of trouble would be a low battery or an unexpected missing message at the keypad.

### Receiving New Software

To update the software for an existing 1131, return the contact to DMP and simply indicate "Update to Current Version" on the RMA tag. The update will be done as a Warranty Repair at no charge, regardless of when the contact was purchased. If a contact is returned for other repair needs, this update will be done automatically as a standard part of the repair. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282. In addition to the software update, new batteries will be supplied when the unit is returned to you.

