

1100R Wireless Repeater February 2009

Version 106 Update

Effective February 2009, all 1100R Wireless Repeaters are being manufactured as Version 106 (1/16/09) software. This version is an update from the Version 106 (11/6/08) software previously shipped and contains updated operation.

Updated Operation

House Code

The 1100R now communicates with the receiver when the system is using house code 1. All House Codes, 1 - 50, are now supported.

Ordering the New Software

To update the software in an existing 1100R Wireless Repeater, return the repeater to DMP and simply indicate "Update to Version 106" on the 6-digit RMA tag. The update will be done under warranty at no charge, regardless of when the repeater was purchased. If a repeater is returned for other repair needs, this update will be done automatically as a standard part of the repair. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282.

