

## Remote Link and System Link January 2010

---

### Version 1.52 Software Update

Effective January 2010, all Remote Link and System Link software is being manufactured as Version 1.52 (1/18/10). This version is an update from the Version 1.52 (1/7/10) previously shipped and contains updated operation.

### Updated Operation

\*\*\*The following issues only occur in the recently released Remote Link Version 1.52 (1/7/2010).\*\*\*

#### Retrieving Communication Programming

Remote Link Version 1.52 (1/7/2010) was unable to properly retrieve communication programming from XR500 panels Version 121 and older. The Remote Link communication programming options screen for the panel being retrieved would be blank or show default settings.

Note: The programming in the control panel was not affected by this issue.

#### Remote Arming

Remote Link Version 1.52 (1/7/2010) was unable to remotely arm any XT Series or XRSuper6, XR20, or XR40 control panels. When remote arming was attempted, Remote Link would display an error window with no additional information displayed in the window. Choosing OK allowed the user to close the window and then perform other tasks.

### Obtaining the New Software

Remote Link Version 1.52 is available for download free of charge on the DMP Dealer Direct Website at <http://dmp.com/dealer>.