

XT30 and XT50 Series Panels May 2010

Software Update

Effective May 2010, all XT30 and XT50 Series panels are being manufactured with Version 103 (5/4/10) software. This version is an update from the Version 103 (12/29/09) software previously shipped and contains new features and updated operation.

Features

984 Command Function

A new option has been added to the 984 Command Function display menu that allows the panel to perform cell diagnostics when TEST is selected.

TEST: This option tests each function of the panel's cellular communication. The tests proceed until a function does not pass, or until all have been tested with positive results. The progress displays during each test.

Swinger Bypass

The Swinger Bypass option in Zone Information now allows two (2) zone alarms, troubles or local trips before bypassing on the third trip.

Updated Operation

★ ★ ★ IMPORTANT UPDATE INFORMATION ★ ★ ★

Cellular Communication

On rare occasions, the cellular modem of the XT30 or XT50 could fail to communicate with the APN of the cellular network causing the panel's cellular communication to be disabled. The central station would be aware of this when the daily test message was missed at the central station. Previously, the panel required a reset to resume communication. Now the cellular modem automatically resumes communication with the cellular APN.

Obtaining the New Software

XT30 and XT50 software updates are available for download free of charge on the DMP Dealer Direct Website at <http://dmp.com/dealer>.