

630F Remote Fire Command Center

August 2011

Version 303 Software Update

Effective August 22, 2011 all 630F Remote Fire Command Centers are being manufactured with Version 303 (8/17/11) software.

Updated Operation

System Trouble Display

Version 303 (8/17/11) software now displays "System Trouble" at the keypad 25 seconds after the keypad stops receiving polls from the panel. This was adjusted to comply with ULC fire monitoring requirements in Canada.

Previously, the delay was 90 seconds.