

Remote Link and System Link October 2013

Version 1.68 Software Update

Effective October 15, 2013, all Remote Link and System Link software is being manufactured as Version 1.68 (10/11/13). If your current Remote Link or System Link software is previous to Version 1.46, update to Version 1.59 before updating to 1.68 (10/11/13).

Important Information: To provide better scalability for growth, SecureCom Wireless has upgraded servers used to provide dealers remote programming of panels over a cellular connection. The SecureCom Wireless server upgrades were completed in November 2012. Older versions of Remote Link prior to version **1.59 (6/24/11)** no longer have the ability to remote program through a panel's cellular connection. If using an older Remote Link version and your company remote programs through a panel's cellular connection, a Remote Link update is required. There is no requirement to update for remote programming if using Remote Link Version 1.59 (6/24/11) or higher.

Updated Operation

Zone Status

Previously, when Zone Status was requested from the System Status window, Remote Link incorrectly requested the status of the same zone from the panel multiple times and failed to advance to the next zone. The status of the remaining zones could be requested by entering the next zone number in the Start at Zone field and clicking Request.

Obtaining the New Software

Remote Link and System Link Version 1.68 (10/11/13) updates are available for download free of charge on the DMP Dealer Direct Website at <http://dmp.com/dealer>.