

Version 107 (11/18/20) Update

Effective December 2nd, 2020, all 1168 Wireless Smoke/CO/Low Temp Detectors are being shipped with Version 107 (11/18/20) software.

Improved Battery Life Efficiency

Version 107 improves the battery life of 1168 Wireless Smoke/CO/Low Temp Detectors by increasing the efficiency of wake cycles. These changes reduce battery drainage considerably when the detector is out of sync and attempts to confirm reconnection to a receiver.

Obtaining the New Software

1168 Wireless Smoke/CO/Low Temp Detectors with Version 107 firmware can be ordered by contacting DMP Customer Service at 1-866-266-2826 or by visiting buy.dmp.com.

Existing devices with prior versions of firmware can be updated to the newest version by following the standard DMP process for repair.