



FEATURE UPDATE | FEBRUARY 2021

Version 211 Date Code Update

Updated Version 211 (2/9/21) firmware is now available on Dealer Admin (dealer.securecomwireless.com) or for download at DMP.com/Dealer_Direct.

Effective March 8th, 2021, all XR Series Panels are being manufactured with updated Version 211 (2/9/21) firmware.

Improvements

DNS Reset Improvement

Previously when updating to Version 211 (1/12/21), a very small subset of panels would receive an error when requesting DNS resolution. This error caused a panel reset in order to clear the DNS error. The DNS stack has been improved to prevent any panel resets from occurring.

Burglary Zone Test Enhancement

With updated Version 211 (2/9/21), all XR150/XR550 Series panels have access to the **Burg** test located in the **System Test** menu. This allows users to test their Burglary zones without having to reset the panel.

Obtaining the New Firmware

XR Series firmware updates are available, free of charge, on Dealer Admin (dealer.securecomwireless.com) or DMP.com/Dealer_Direct.