

HARDWARE UPDATE

Hardware Update

Effective October 30th, 2019, all 1100XH High Power Wireless Receivers are being manufactured with Level 103 Hardware and Version 205 firmware.

Features

Design Improvements

The 1100XH now features an internal spiral antenna in place of the J-pole wire antennas. There are no changes to operation or performance as a result of this hardware update. The overall design has been improved and streamlined for your benefit.

Wireless Speed Improvements

Version 205 features wireless speed improvements. These changes improve wireless response time on 9800 Graphic Touchscreen Keypads and 1134 Wireless Wiegand Modules.

Additional Keypad Support

Version 205 allows up to seven wireless keypads and 1134 Wireless Wiegand Modules to communicate with XR150/XR550 Series panels using the receivers. To support this feature, the control panel must be updated to Version 191 or higher.

Obtaining the New Firmware

The new 1100XH High Power Wireless Receivers can be ordered by contacting DMP Customer Service at 1-866-266-2826 or by visiting buy.dmp.com.