

XR150/XR550 Series Control Panels

September 2016

Version 113 Firmware Update

Version 113 (9/9/16) firmware is now available for download on the DMP Dealer Direct Website at <http://dmp.com/dealer>.

Effective October 10, 2016, all XR150/XR550 Series panels will be manufactured with updated Version 113 (9/9/16) firmware. As of November 18, 2016, inventory for the XR150/XR550 Series panels will be completely updated.

Features

Invalid Code Reporting

For XR150/XR550 Series panels (Version 113 or higher), Remote Link™ software now displays a code output for Access Denied: Invalid Code events. The Invalid Code Reporting feature shows code output of card reads that are not programmed in the system.

A code output is displayed any place within Remote Link that allows an operator to see Events. This includes Standard and Advanced Reports (printed or viewed) and Real Time Events.

To view access reports, navigate to these locations within Remote Link:

- File → Print → Events
- File → Print → Advanced Reports (if enabled)
- System → Real Time Events (if enabled)

The code output displays as information added on to the existing specific event (see below).

Previously, Remote Link displayed Access Denied: Invalid Code events as:

9:20 AM Door: 1 DEVICE 1 Access Denied: Invalid Code

Now, with Version 113, Access Denied: Invalid Code events display as:

9:20 AM Door: 1 DEVICE 1 Access Denied: Invalid Code: 123456

Note: Panels only store codes for the last ten Door Access Denied Events. The panel will not be able to send more than the most recent ten codes when Events are retrieved.

Inactive User Audit

The Inactive User Audit's maximum time period has been increased from 365 days to 425 days. After a user code has been inactive for the selected time period (up to 425 days), a message is sent to the Central Station.

Default Fire Bell Action

The default bell action for fire alarms has been changed from Pulse to Temporal.

Obtaining the New Firmware

XR150/XR550 Series firmware updates are available for download free of charge on the DMP Dealer Direct Website at <http://dmp.com/dealer>.

2G Network Shutdown

Do you have all your 2G accounts upgraded already? The end of 2G is near. On December 31st, 2016, all AT&T 2G systems will cease to operate. This will affect your XT and XTL Series panels with built-in GSM cell modules, as well as your 263G and 463G cellular modules.

For all SecureCom Wireless customers, we have customized reports available to you that list your current 2G communicators still in use.

Get your company's custom report by emailing CustomerService@securecomwireless.com or calling us at 877-300-8030. Find out which of your accounts are still on 2G and update them before it's too late.

Visit <https://www.dmp.com/2GSunset/> for more information.