

866 Polarized Bell Module Hardware Update

January 14, 1998**Hardware Update**

Effective January 30, 1998 all 866 Polarized Bell Modules will be shipped from the factory with updated hardware.

Operational Update Feature**Bell Silence Switch Trouble/Restore Operation**

The Silence switch on the 866 module allows technicians to test or perform maintenance on the fire system without sounding the fire alarm notification devices. Placing this switch to the Silence position and removing a wire from the contacts on terminals 7 and 8 prevent Bell Trouble/Restore messages from being sent to the panel. Now, placing the Bell Silence switch to the silence position is all that is needed. Removing a wire from the contacts on terminal 7 and 8 is no longer required.

Updating 866 Module

If you have any previous versions of the 866 Polarized Bell Module and would like them upgraded, you may send these to DMP Technical Support (888-4DMPTEC). DMP technicians will update the 866 module at no charge to you.