

Remote Access™ Software Update

December 23, 1997

Version 1.05 Software Update

Effective December 29, 1998 Remote Access™ is being shipped from the factory with version 1.06 (12/23/97) software. This version is an update from the 1.05 (10/28/97) software previously shipped and contains two new operational features to the program.

New Operational Features

Device Programming with Model 485

When the 485 Access Control Expansion Card is used with the XR200 Command Processor™ Panel device programming will now support 16 addresses. Previously, not all 16 devices were requested by Remote Access™.

User Code Programming with Partitions

When user codes are requested by Remote Access™ for partitions 2,3 or 4 they will be displayed with the appropriate partition number. Previously, all user codes were displayed as Partition 1.

Existing Operational Issues

Several other operational issues currently exist with Remote Access™ that are not being addressed by this release. There are schedules to be addressed in the next release of Remote Access™ in April 1998.

Off-line User Code Deletions

When a user code is deleted in a file prior to connecting with a panel, then the file is sent to the panel, the user code is not deleted. Instead, all user code deletions must be done while on-line with the panel.

Remote Key Field Does Not Show Asterisks

When a level six operator is requesting panel account information prior to a connect, spaces are displayed instead of asterisks if a key exists. The key is still operational even though the asterisks do not appear.

Fire Bell Output Programming

When panel programming is printed for an XR200 or XR200/485 system, Fire Bell Output [rogramming is not currently included. The programming in the panel operates properly, but the option is not printed.

Leading Zeros in Remote Key

Panels which have a leading zero(s) will not allow a remote connect. Leading zeros should be removed from panel remote keys.

Areas of Access Not Printed for XR20

The areas of Access and Area programming are not currently printed for XR20 panels. The options are still operational, but are not printed.

Ordering the New Firmware

To update your current Remote Access™ software to version 1.05 (12/23/97), please call Inside Sales at 1-800-641-4282 and ask for the Remote Access™ Update. There is no charge for the update.