

TECHNICAL UPDATE | FEBRUARY 2025

Version 243 Update

Updated Version 243 (2/25/25) firmware is now available for XR Series Control Panels.

Power Trouble

Previously, the panel acknowledged power trouble from the 1100T but only sent a Restore report to the receiver without an initiating Trouble report. This occurred when the following conditions were met:

- **Power Fail Delay** was set to the default of 1 hour on the panel.
- The 1100T experienced power trouble for more than 3 minutes but less than 1 hour.

Now, the panel reports power trouble and its restoral events to the receiver for the 1100T.

Door Schedules

This update allows **Door Schedules** to operate correctly when only a start time or only an end time is entered.

Custom Actions

This update allows multi-swipe options in **Custom Actions** to properly arm common areas when all other areas are armed.

Obtaining the New Firmware

XR Series firmware updates are available, free of charge, on Dealer Admin (dealer.securecomwireless.com) or for download from DMP's [Product Software Downloads](#).