

### Version 1.4.5 Update

Effective November 13th, 2019, all SCS-VR™ software will be manufactured with Version 1.4.5 (11/12/19). The following features are available:

### Features

#### Panels Tab Improvements

The **Panels** tab now includes the option to display messages for the number of **Missing Panels** and **Substituted Panels** when the respective checkboxes are selected.

To show missing and substituted panels at the bottom of the **Panels** tab, go to **Program Files > SCS-VR > Properties**. Open **system.properties** and add the following line: `show_panel_summary=true`. Save and close the properties file.

#### IPv6 Support for Outbound Automation

SCS-VR now supports the use of IPv6 addresses for outbound automation in **Groups > Outbound**.

#### Console Log File Rollover Improvements

Console log files are now stored separately from the service log. This feature allows the console log to roll over while the SCS-VR service is still running.

#### UDP Message Failover

Messages sent over UDP now fail over to a secondary database on receivers that have multiple databases configured.

#### Automatically Discard Unrecognized Messages

At times, you may have received unrecognized modem AT commands in the **Message Log** tab. Those unrecognized messages are now discarded automatically.

### Obtain the New Software

Contact the Software Support Team in DMP Technical Support at 1.888.436.7832 for information on updating to SCS-VR Version 1.4.5 (11/12/19).