

HARDWARE UPDATE

Hardware Update

Effective September 25th, 2019, all 1100X Series Wireless Receivers are being manufactured with Level 103 Hardware and Version 205 firmware.

Features

Design Improvements

The 1100X now features an internal spiral antenna in place of the J-pole wire antenna. There are no changes to operation or performance as a result of this hardware update. The overall design has been improved and streamlined for your benefit. The 1100X also features a new 4-position terminal block for connection to an XR Series panel. This eliminates the need for a 4-position harness.

Wireless Speed Improvements

Version 205 features wireless speed improvements. These changes improve wireless response time on 9800 Graphic Touchscreen Keypads and 1134 Wireless Wiegand Modules.

Additional Keypad Support

Version 205 allows up to seven wireless keypads and 1134 Wireless Wiegand Modules to communicate with XR150/XR550 Series panels using the receivers. To support this feature, the control panel must be updated to Version 191 or higher.

Obtaining the New Firmware

The new 1100X Series Wireless Receivers can be ordered by contacting DMP Customer Service at 1-866-266-2826 or by visiting buy.dmp.com.