.

# **Remote Link and System Link**

# July 2015

### Version 1.75 Software Update

Effective July 9, 2015, all Remote Link and System Link software is being manufactured as Version 1.75 (7/8/15). If your current Remote Link or System Link software is previous to Version 1.46, update to Version 1.59 before updating to 1.75 (7/8/15).

#### **Features**

#### **Remote Updates**

Remote Link now supports remote firmware updates over network for XT30/XT50 Series Control Panels operating with Version 123 or higher firmware and the soon to be released Level M hardware.

For more information on this feature refer to the XT30/XT50 Level M Hardware Update (TU-0797).

#### CellComSL Series Ademco/Honeywell ECP

A new option, Keypad Input, is now available in System Options for CellComSL Series Communicators operating with Version 123 or higher firmware. This option supports Ademco/Honeywell ECP Bus Communication. The CellComSL Series Communicator requires the soon to be released Level E hardware.

For more information on this feature refer to the following Feature and Hardware Updates:

- CellComSL Version 123 Feature Update (TU-0785)
- CellComSL Level E Hardware Update (TU-0787)

Also refer to Keypad Input and Ademco/Honeywell ECP Connection in the CellComSL Installation/Programming Guide (LT-1339).

### **Obtaining the New Software**

Remote Link and System Link Version 1.75 (7/8/15) updates are available for download free of charge on the DMP Dealer Direct Website at <u>http://dmp.com/dealer</u>.

C:\Users\De	sktopWT50.RU	
×T50 to version: 123	[06/10/2015]	
itatus		

Options	Time Change	
🥅 Reset Swinger Bypass	Hours from GMT	6
Miscellaneous Options	🛛 🔽 Time Change	
Swinger Bypass Trips 2	Delays	
Keypad Input	Entry Delay 1	30
	Exit Delay	60
	Cross Zone Time	C
	Power Fail Delay	1

