

XR150/XR350/XR550 Series Control Panels

August 2014

Version 106 Software Update

The XR150/XR350/XR550 Version 106 (7/28/14) software is now available for download on the DMP Dealer Direct Website at <http://dmp.com/dealer>.

Effective August 22, 2014, all XR150/XR350/XR550 Series panels will be manufactured with updated 106 (7/28/14) software. As of October 3, 2014, inventory for the XR150/XR350/XR550 panels will be completely updated to Version 106 (7/28/14) software.

Feature

MyVirtualKeypad.com™ Browser

Version 106 (7/28/14) supports new features available in Version 1.4.0 (8/1/14) of the Virtual Keypad Browser. Users will now have the ability to program panel schedules and lock and unlock doors. For more information see MyVirtualKeypad.com Browser Version 1.4.0 (8/1/14) Technical Update TU-0749.

Updated Operation

Wireless trouble

Immediately after programming, some systems with more than 30 wireless transmitters, could display WIRELESS TROUBLE at the keypad and the wireless zones could not communicate with the panel.

Area System Disarming

This issue only occurred if all of the following conditions were met:

- The control panel was operating with Version 105 software
- A burglary alarm had occurred
- The Bell Cutoff time had not expired
- After entering their code at a keypad, the user chose to cancel the alarm

If all conditions were met, ALL areas programmed for that keypad in Display Areas of Device Setup would be disarmed. This occurred even if the user did not have authority to disarm some areas.

Output Real-Time Status

Previously, Real-Time Status messages were not sent from the panel to Entré or PC Log Reports when an output was turned on or off as the result of a schedule.

Obtaining the New Software

XR150/XR350/XR550 Series software updates are available for download free of charge on the DMP Dealer Direct Website at <http://dmp.com/dealer>.

