

1121 and 1124 Hardware Update

July 2007

Hardware Update

All 1121 and 1124 Wireless PIR Transmitters will now be manufactured with updated Level F hardware.

Updated Hardware

Low Battery Detection

New Level F hardware for the 1121 and 1124 Wireless PIR transmitter corrects an issue where a low battery condition of a transmitter could not be detected and therefore a low battery message was not sent to the receiver. A transmitter missing would still be indicated when the battery was completely depleted. The typical battery life is not affected.

Obtaining Hardware Level F

To update, return any older Level C, D or E 1121 or 1124 PIRs to DMP and simply indicate "Update to Latest Hardware Level F" on the RMA tag. The update will be done as a Warranty Repair at no charge, regardless of when the 1121 or 1124 was purchased. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282.

The 1121 was originally released for sale in March of 2005. The 1124 was originally released in March of 2006. Both products were most recently built with Level E Hardware until April of 2007.



Model 1121



Model 1124

