

## XR100 and XR500 Series October 2008

---

### Version 202 Software Update

Effective October 2008, all XR100 and XR500 Series Command Processor™ panels are being manufactured with Version 202 (10/8/08) software. This version is an update from the Version 202 (9/5/08) software previously shipped and contains updated operation.

Remote Link Version 1.44 (8/5/08) or higher is **required** to support the panel Version 202 features. Remote Link Version 1.44 is available for download free of charge on the DMP Dealer Direct Website at <http://dmp.com/dealer>.

### Updated Operation

#### Substitution Error

Previously, when an XR100 or XR500 Series control panel was updated from Version 121 (11/8/07) to Version 202 (9/5/08) and SUB CODE (substitution checking) was enabled in communication programming, a Panel Substitution Alarm (S58) was generated at the SCS-1R receiver. This update allows a panel to be updated from Version 121 (11/8/07) to Version 202 without a Panel Substitution Alarm being generated at the receiver.

### Obtaining the New Software

XR100 and XR500 Series software update Version 202 (10/8/08) is available for download free of charge on the DMP Dealer Direct Website at <http://dmp.com/dealer>.

Remote Link Version 1.44 (8/5/08) or higher is **required** to support the panel Version 202 features. Remote Link Version 1.44 is available for download free of charge on the DMP Dealer Direct Website at <http://dmp.com/dealer>.