

FEATURE UPDATE | MAY 2021

Version 309 Firmware Update

DMP is now shipping 7000 Series Keypads manufactured with Version 309 firmware.

Improved Request to Exit (REX) Behavior

A Zone 3 REX is inhibited for three seconds after the keypad reads a card and a door strike occurs. 7000 Series keypads no longer inhibit Zone 3 REX when the access point's state changes to open.

- When shorted, the lock relay will not activate and the Zone 2 Bypass begins (normally with electric strikes)
- When open, the lock relay will activate for the programmed REX time and the Zone 2 Bypass begins (standard with magnetic locks)

Obtaining the New Software

To order 7000 Series Keypads with updated firmware, contact DMP Customer Service at 1-866-266-2826 or visit Buy.DMP.com.