

## TECHNICAL UPDATE | APRIL 2023

### Version 221 Update

All XR150/XR550 Series Control Panels are being manufactured with Version 221 (4/19/23) firmware.

### Panel Improvements

Updated Version 221 (4/19/23) resolves an issue where the “No Authority” message would appear when disarming an All/Perimeter system by using the shield.

Updated Version 221 (4/19/23) resolves an issue where the user disarms a system early and the panel rearms in 28 minutes instead of 540 minutes.

Updated Version 221 (4/19/23) resolves an issue where if the user presses the exit shield during an entry delay, the panel will not respond to anything entered on the keypad for 90 seconds.

### Obtaining the New Firmware

XR150/XR550 firmware updates are available, free of charge, on Dealer Admin ([dealer.securecomwireless.com](https://dealer.securecomwireless.com)) or for download from DMP's [Product Software Downloads](#).