



TECHNICAL UPDATE | APRIL 2023

Version 721 Update

All XR150INT/XR550INT Series Control Panels are being manufactured with Version 721 (4/19/23) firmware.

Panel Improvements

Updated Version 721 (4/19/23) resolves an issue where the “No Authority” message would appear when disarming an All/Perimeter system by using the shield.

Updated Version 721 (4/19/23) resolves an issue where the user disarms a system early and the panel rearms in 28 minutes instead of 540 minutes.

Updated Version 721 (4/19/23) resolves an issue where if the user presses the exit shield during an entry delay, the panel will not respond to anything entered on the keypad for 90 seconds.

Obtaining the New Firmware

XR150INT/XR550INT firmware updates are available, free of charge, on Dealer Admin (dealer.securecomwireless.com) or for download from DMP's [Product Software Downloads](#).