

UPDATED FUNCTIONALITY | FEBRUARY 2021

Version 211 (2/5/21) Update

Effective February 15, 2021, all X1 Series Door Controllers will be manufactured with Version 211 (2/5/21) firmware. All X1 Series Door Controllers in the field will update to Version 211 (2/5/21) once they check in to Dealer Admin™.

Improvements

Resolved Unintended Door Operation When Saving a Schedule

Doors will no longer unlock outside of the scheduled open time regardless of when a schedule was sent to the X1 Series Door Controller.

Improved Time Retrieval

Previously, the Door Controller would try twice initially after power up to retrieve the time. If the Door Controller failed then it would wait for 24 hours. With updated Version 211 (2/5/21), the Door Controller will continue to request a time update until it has received a valid response.

Blank SSID

With updated Version 211 (2/5/21), the Door Controller's default SSID and password are now blank to allow the installer to program the desired Wi-Fi settings.

Corrected Invalid Code Sent During Setup

While changing the reader protocol from Wiegand to OSDP, the Door Controller would repeatedly send invalid code until the programming was saved. Updated Version 211 (2/5/21) resolves this issue.