

## XTL and XT30/XT50 Series Panels

October 2010

---

### Software Update

Effective November 2010, all XTL and XT30/XT50 Series Panels are being manufactured with Version 106 (11/1/10) software.

### Updated Operations

#### Receive Cell Messages

A Remote Link session that did not terminate correctly could cause the cellular modem of the panel to not be able to receive connect messages from Remote Link or cellular commands using text messaging. However, this issue did not ever affect the panel's ability to send event messages to the central station receiver or to send SMS/Email messages.

When this issue occurred, a subsequent panel message to the central station receiver would automatically correct the issue allowing Remote Link to connect until the next Remote Link session that did not terminate correctly.

### Obtaining the New Software

XTL and XT30/XT50 Series Panels software updates are available for download free of charge on the DMP Dealer Direct Website at <http://dmp.com/dealer>.