

XR100/XR500 Series

May 2013

Version 212 Software Update

The XR100/XR500 Version 212 (5/6/13) software is now available for download on the DMP Dealer Direct Website at <http://dmp.com/dealer>.

Effective May 13, 2013, all XR100 and XR500 Series panels will be manufactured with updated Version 212 software. As of July 1, 2013, inventory for the XR100 and XR500 panels will be completely updated to 212 (5/6/13) software.

Updated Operation

Burglary Keypad Display

When disarming the system from a burglary keypad that is programmed in Device Setup as DOOR, KYPD or EXP (not FIRE), the keypad no longer briefly displays fire zones that are in an alarm state and haven't been cleared from the fire keypad by a Sensor Reset.

Note: Before this revision, a fire zone that had been cleared from the fire keypad by Sensor Reset no longer display at disarming.

System Message 88 Automatic OK – Unrestored System

The panel's daily test message S88 used for fire systems that could be sent to the Central Station receiver instead of S07, will now only be used and sent if at least one keypad is programmed in Device Setup as FIRE. S88 is only used for fire system communication and sent at the daily test time when a system trouble such as AC Trouble, Battery Trouble or Fire Zone Trouble is displaying at the keypad.

Obtaining the New Software

XR100/XR500 Series software updates are available for download free of charge on the DMP Dealer Direct Website at <http://dmp.com/dealer>.

