

XT and XTL Series Panels

November 2013

Version 116 Software Update

Version 116 (11/14/13) software is now available for download on the DMP Dealer Direct Website at <http://dmp.com/dealer>.

Effective November 19, 2013, all XT and XTL Series panels are being manufactured with updated Version 116 (11/14/13) software. As of December 31, 2013, inventory for the XT and XTL Series panels will be completely updated to Version 116 (11/14/13) software.

Updated Operation

Cell Status

The CELL STATUS option in the DIAGNOSTICS (2313) menu has been revised to provide enhanced trouble shooting guidance:

CDMA Cellular communicators (263C and XTLC Control Panel)

When the Cell Status test ends successfully the keypad now displays CONNECT SUCCESS followed by CELL COMM GOOD. CONNECT ERROR is now displayed if the Cell Status test fails for reasons such as poor signal or incorrect receiver IP address.

If the test fails because the cellular communicator has not been activated the keypad now displays NOT ACTIVATED to indicate that the communicator must be activated before use. See the 263C Installation Guide (LT-1264) or the XTL/XTLC Programming Guide (LT-1108) for information on activating CDMA Cellular Communicators.

GSM and HSPA+ Cellular Communicators (263G and 263H)

When the Cell Status test fails because no SIM card is inserted the keypad now displays NO SIM CARD. Previously, the keypad incorrectly displayed NO MODEM FOUND.

Obtaining the New Software

XT30/XT50 and XTL Series software updates are available for download free of charge on the DMP Dealer Direct Website at <http://dmp.com/dealer>.

