

## CellComSL™ Series Universal Alarm Communicators

December 2015

### Version 123 Firmware Update

Version 123 (11/20/15) firmware is now available for download on the DMP Dealer Direct Website at <http://dmp.com/dealer>.

Effective December 21, 2015, all CellComSL Series Universal Alarm Communicators will be manufactured with updated Version 123 (11/20/15) firmware. The updated firmware will begin shipping as current stock is depleted which is estimated to occur by December 28, 2015.

### Updated Operation

#### Communication Failure Output

Previously, the Communication Failure Output was not turned on when the check in and fail time was set to 10 minutes or less. The Communication Failure Output is now turned on after four failed attempts to send a message regardless of Check in or Fail time.

#### Ademco/Honeywell ECP Bus Improvements

The operation of the ECP connection has been enhanced to correct the following:

- The CellComSL would not disarm the Ademco/Honeywell control panel when a trouble message was displayed on the Ademco/Honeywell keypad.
- When a valid code was entered at a Z-Wave Lock, the CellComSL would not disarm the Ademco/Honeywell control panel using the ECP connection.

### Obtaining the New firmware

CellComSL Series firmware updates are available for download free of charge on the DMP Dealer Direct Website at <http://dmp.com/dealer>.