

1122 Wireless PIR Motion Detector & 1128 Wireless Glassbreak



FEATURE UPDATE

Version 2.0.0.2 Update

Effective September 21, 2020, all 1122 Wireless PIR Motion Detectors are being shipped with Version 2.0.0.2 firmware.

Effective September 22, 2020, all 1128 Wireless Glassbreak Detectors are being shipped with Version 2.0.0.2 firmware.

Wireless Improvements

Improved Communications

Version 2.0.0.2 firmware improves the communication with all DMP 1100 series receivers.

Obtaining the New Firmware

The 1122 Wireless PIR Motion Detectors and 1128 Wireless Glassbreak Detectors with Version 2.0.0.2 firmware can be ordered by contacting DMP Customer Service at 1-866-266-2826 or by visiting buy.dmp.com.

Existing devices with prior versions of firmware can be updated to Version 2.0.0.2 by following the standard DMP process for repair.