

### Version 1.4.6 (11/19/20) Date Code Update

Effective November 30th, 2020, all SCS-VR Virtual Receiver Software will be manufactured with Version 1.4.6 (11/19/20) software.

#### CID Message Color Coding

Improvements have been made to standardize the color coding scheme of CID messages with the color coding used for Serial 3 messages.

#### CID Account Numbers with Leading Zeros

When a message was sent to the receiver in raw CID format and the panel account number contained a leading zero, SCS-VR would remove the leading zero. This behavior shifted the string, which could prevent automation software from translating it properly. This issue is resolved with this date code release.

#### International Panels—Zone Tamper (Zi) Message Sorting

This date code fixes an issue for panels with firmware Version 702 where zone tamper (Zi) messages would not be displayed at the top of the **Message Log**.

### Obtaining the New Software

SCS-VR Version 1.4.6 (11/19/20) is now available for download at [DMP.com/Dealer\\_Direct](https://DMP.com/Dealer_Direct).