



NEW FEATURES ⊕ | **UPDATED FUNCTIONALITY** ⬆ | **DECEMBER 2021**

Version 213 Update

Version 213 (12/17/21) firmware is now available on Dealer Admin (dealer.securecomwireless.com).

Effective January 17th, 2022, all XR Series Panels are being manufactured with Version 213 firmware.

Panel Features

Zone Expansion Module Programming

Version 213 supports changes to addressing zone expansion modules, starting with the 711S. The modules will be able to be programmed into the panel via a 10-digit serial number instead of rotary switches. A new **Expander Serial Number** prompt has been added in **Zone Information** to allow a serial number to be entered for addressing. This feature requires XR Version 213 and 711S Level 102 hardware with Version 101 firmware.

Panel Improvements

Improved Central Station Test Failure Procedure

With Version 213, the panel will send the user a notification in a future version of Dealer Admin if the chosen communication path has failed to test with the central station. This will allow users to run reports and to run a communication test to verify whether that path is down.

DHCP Enhancement

XR Version 213 allows for the panel to be set to DHCP, but will still be able to program the specific DNS the panel should use. This helps to overcome any DNS that are not resolving as they should allows a specific IP address to be programmed for DNS resolution troubleshooting.

Wireless Key Fob Improvement

XR Version 213 ensures that 1144 Series Key Fobs do not allow arming or disarming when the associated user code is set to inactive.

Wireless Tamper Report Improvement

Previously, if a wireless receiver tamper was activated, all of the wireless zones would be set to open. This would cause the panel to send trouble messages to the central station for every zone that reported to the receiver.

With Version 213, if the tamper is activated, the panel will only send a supervised trouble message.

Supporting Software Updates

- Dealer Admin Version 2.74.0
- Virtual Keypad Browser 2.38.0
- Virtual Keypad App 6.41

Obtaining the New Firmware

XR Series firmware updates are available, free of charge, on Dealer Admin (dealer.securecomwireless.com) or for download from DMP's [Product Software Downloads](#).