



FEATURE UPDATE | APRIL 2022

Version 213 Date Code Update

Effective May 2nd, 2022, all XR150/XR550 are being manufactured with updated Version 213 (4/8/22) firmware.

Effective May 9th, 2022, all XT30/XT50, XTLplus, and XTLtouch Panels and COM Series Communicators are being manufactured with updated Version 213 (4/12/22) firmware.

Panel Features

Improved Cellular Modem Reporting

Previously with some Verizon cell modems, if the modem was powered on before activation was complete with SecureCom, the Verizon cellular tower would block that modem from connecting for up to two hours and would cause a “Not Registered” message at the keypad.

With updated Version 213, a new command will be sent when the modem is powered up to make sure that the connection can be established and no communication delays will occur.

Obtaining the New Firmware

Panel Series firmware updates are available, free of charge, on Dealer Admin (dealer.securecomwireless.com) or for download from DMP's [Product Software Downloads](#).