



## TECHNICAL UPDATE | MAY 2023

### Version 721 Update

All XT30INT, XTLplusINT, and XTLtouchINT Series Control Panels are being manufactured with Version 721 (4/10/23) firmware. Updates are also available on Dealer Admin ([dealer.securecomwireless.com](https://dealer.securecomwireless.com)) or for download from DMP's [Product Software Downloads](#).

### Panel Improvements

Updated Version 721 (4/10/23) resolves an issue where the control panel would occasionally stop responding to the Wi-Fi network after receiving a message with a "VLAN Tag."

Updated Version 721 (4/10/23) resolves an issue where the control panel would occasionally send stored messages with the incorrect time stamp.

Updated Version 721 (4/10/23) resolves an issue where the control panel would occasionally not automatically rejoin the Wi-Fi network after losing connection.

### Obtaining the New Firmware

Firmware updates are available, free of charge, on Dealer Admin ([dealer.securecomwireless.com](https://dealer.securecomwireless.com)) or for download from DMP's [Product Software Downloads](#).