

XT30/XT50/XTL Series Panels

June 2015

Version 123 Firmware Update

Version 123 (6/10/15) firmware is now available for download on the DMP Dealer Direct Website at <http://dmp.com/dealer>.

Effective July 6, 2015, all XT30/XT50/XTL Series control panels will be manufactured with updated Version 123 (6/10/15) firmware. As of August 14, 2015, inventory for the XT30/XT50/XTL panels will be completely updated to Version 123 (6/10/15) firmware. This includes the XTLC, XTLN, and XTLN-WiFi panels.

Features

1164 Wireless Synchronized Smoke Detector

XT30/XT50/XTL Series operating with Version 123 (6/10/15) firmware now supports the synchronized sounder operation of the soon to be released 1164 Wireless Synchronized Smoke Detector.

An XT30 using an 1100D Wireless receiver operating with Version 203 (11/26/14) is required for the operation of the 1164 Smoke Detector.

See TU-0794 for more information on 1100 Wireless Receivers compatibility with the 1164 Smoke Detector.



Obtaining the New firmware

XT30/XT50/XTL Series firmware updates are available for download free of charge on the DMP Dealer Direct Website at <http://dmp.com/dealer>.