

SCS-150 Processor

November 2012

Version 103 Software Update

SCS-150 Version 103 (10/08/12) software is now available for download on the DMP Dealer Direct Website at <http://dmp.com/dealer>.

Effective 11/2/12, all SCS-150 Processor Cards are being manufactured with Version 103 (10/08/12) software. The updated software will begin shipping as current stock is depleted and is estimated to occur in early December 2012.

Updated Operation

Receiver Network Line Card Programming

After the SCS-150 sends programming to the SCS-104 Line Card, network line programming changes are now correctly applied. Previously, if Network Line Enable for the SCS-104 was set to YES, and then changed to NO, the SCS-104 would continue to receive network messages until the line card power was cycled.

This issue did not occur for digital dialer programming of the SCS-104 Line Card.

Note: Both SCS-150 and SCS-104 must be updated for this change to take effect. Please see Technical Update TU-0659 for SCS-104 details.

Obtaining the New Software

SCS150/UPDATE SD cards may be obtained by calling DMP Customer Service at 1-800-641-4282 or from buy.dmp.com. The update files can also be downloaded from the DMP Dealer Direct Website at <http://dmp.com/dealer> and saved onto an SD card. See the SCS-150 Update Installation Sheet (LT-1056) for complete instructions on how to program an SD card for SCS-150 updates.