

SCS-104 Line Card October 2011

Version 100 Software Update

Effective October 21 2011, all SCS-104 Line Cards are being manufactured and shipped with Version 100 (10/3/11) software.

Updated Operation

Time Updates Over Network

When a panel requests a time update from the SCS-104 over network communication, the correct month is now sent in the update. Previously, the month number sent was the number for the prior month.

Obtaining the New Software

To update, return any older SCS-104 line cards to DMP and simply indicate "Update to Latest Version Software" on the RMA tag. The update will be done as a Warranty Repair at no charge, regardless of when the line card was purchased. If you need RMA tags, contact DMP Customer Service at 1-800-641-4282.

In addition, Remote Link Version 1.61 due to release in mid-November will provide the capability to update the SCS-104 card in the field using a 399 cable.

REPAIR AUTHORIZATION

DO NOT SEND METAL CABINETS WITH CIRCUIT BOARD

157668

PRINT CLEARLY THIS IS YOUR RETURN SHIPPING DOCUMENT.

Company: ALAMCO NAME

Address: ADDRESS

City: _____ State: _____ Zip: _____

Model No.: MODEL S/N: _____

Installation Site: _____

Describe Problem: UPDATE TO LATEST SOFTWARE

Preferred return shipping method: _____

FOR DMP USE ONLY

Received: _____ By: _____ Code: _____

Repaired: _____ In-Circuit Test: _____ Functional Test: _____

Parts Replaced: _____ By: _____ Code: _____

PCB Housing Box

Final Test: _____ By: _____

Shipped: _____ By: _____

Date Entry: _____ By: _____

KEEP THIS STUB FOR YOUR RECORDS

Repair Voucher

Model No.: 157668 S/N: _____

Installation Site: _____