

Remote Link and System Link May 2009

Version 1.48 Software Update

Effective May 2009, all Remote Link and System Link software is being manufactured as Version 1.48 (5/26/09). This version is an update from the Version 1.48 (5/7/09) previously shipped and contains updated operations.

Updated Operation

Serial Port Programming

The Auxiliary (A2) port Usage drop-down has been updated to display 'Auxiliary' as the default selection. Previously, this field was blank.



Programming Zone

Remote Link now properly allows zone 80 to be programmed for new XT50 Series panel accounts using software Version 101. This did not affect pre-existing accounts.

Previously the following error message would display: "This zone requires Built-in 1100 wireless to be enabled in the System Options menu".

Obtaining the New Software

Remote Link Version 1.48 is available for download free of charge on the DMP Dealer Direct Website at <http://dmp.com/dealer>.