XR SERIES VERSION 231 (1/25/24)

XR150/XR550



TECHNICAL UPDATE | JANUARY 2024

Version 231 Update

Updated Version 231 (1/25/24) firmware is now available on XR150/XR550 Series panels.

Panel Improvements

XR to X1 Communication

Allows sites with both X1 Series Controllers and XR Series panels to operate cohesively. This will allow X1 systems to communicate with XR systems over the selected network as well as arm and disarm areas in an XR Series panel. Users can also initiate a fire exit and lockdown in an XR Series panel. For more information, refer to the <u>Panel to Panel Communication Helpfile</u>.

XR to XR Communication

Allows multiple XR Series panels within a single site to operate cohesively. This will allow XR systems to communicate with each other over the selected network as well as simultaneously arm and disarm areas on multiple XR Series panels. Users can also initiate a fire exit and lockdown across all connected XR Series panels. For more information, refer to the <u>Panel to Panel Communication Helpfile</u>.

8860 Series Keypad Support

XR150/XR550 Series panels have been updated to support the upcoming feature for 8860 Series keypads to communicate wirelessly with the panel via Wi-Fi network.

7830F Keypad Support

7830F keypads can now be used with XR150/XR550 Series panels.

OSDP Tamper Message Support

If there is an OSDP reader connected to an XR system and a tamper occurs at the reader, a tamper message will be sent to the Monitoring Center.

Default Closing Code Update

XR150/XR550 Series panels that are set up as an Area System will now have the Closing Code option defaulted to YES.

1136 Annunciation

If the Zone Monitor feature was enabled on the panel and an 1100T Wireless Translator was installed, the 1136 Chime Module would not chime for entry or exit delays.

With updated Version 231, the 1136 will chime for entry or exit delays.

Obtaining the New Firmware

XR150/XR550 firmware updates are available, free of charge, on Dealer Admin (<u>dealer.securecomwireless.com</u>) or for download from DMP's <u>Product Software Downloads</u>.