

TECHNICAL UPDATE | JUNE 2025

Version 252 Update

Updated Version 252 (5/21/25) firmware is now available for XR Series Control Panels.

734N Network Connection

Previously, when several 734N Network Access Control Modules were programmed to an XR Series Control Panel, if a network outage occurred, the 734N modules did not always reconnect to the panel once network was restored. Now, 734N modules properly reconnect to the panel after a network outage.

Obtaining the New Firmware

XR Series firmware updates are available, free of charge, on Dealer Admin (dealer.securecomwireless.com) or for download from DMP's [Product Software Downloads](#).