

Version 231 (6/27/25) Update

X1 Series Controller software has been updated to Version 231 (6/27/25).

Reader LED

Previously, when pressing the Request to Exit (REX) button on the X1, the reader LED turned red after a short time. This update allows the LED to remain green while the door is unlocked.

Reader Sounder

Previously, for XD Door Control Module operations, when a valid card read unlocked a door after a scheduled unlock time, the reader sounded until the user locked, then unlocked the door in Virtual Keypad.

This update allows readers to correctly sound during the programmed strike time only.

More Information

To learn more about automatic updates to your X1 Controller, see [Dealer Admin Help File: Update an X1 Controller](#).