

TECHNICAL UPDATE | JULY 2025

Version 252 Update

Updated Version 252 (7/7/25) firmware is now available for XT75 Control Panels.

Bell Circuit

This update improves bell circuit monitoring to confirm the panel bell is only active during alarm conditions.

Exit Delay Restart

Previously, the **Exit Delay** restart feature was enabled when **Occupied Premises** was set to **YES** and disabled when **Occupied Premises** was set to **NO**. Now, **Exit Delay** restart is always enabled.

Obtaining the New Firmware

XT75 firmware updates are available, free of charge, on Dealer Admin (dealer.securecomwireless.com).