

TECHNICAL UPDATE | MAY 2019

Technical Update

Effective May 20th, 2019, all DualCom Communicators will be manufactured with Version 191 (05/02/19). Updated units will begin shipping late-June.

Updated Functionality

ECP Programming Improvement

DualCom Version 191 (05/02/19) now supports programming the Honeywell® VISTA® 128 panel using ECP programming. You can connect DualCom to the VISTA 128 ECP bus, and with Remote Link™ Version 1.92, you can program the Honeywell panel remotely using the Compass® downloading software. Use Remote Link Version 1.92 to fully program the host panel on the ECP bus. Remote Link will intercept communications from Compass and send it to DualCom, which passes these communications along the ECP bus.

Obtaining the New Firmware

Firmware updates are available for download, free of charge, on the DMP Dealer Direct website at DMP.com/Dealer_Direct.

If you have any questions or concerns about implementing this firmware update, please contact DMP Technical Support by calling 1.888.436.7832 or emailing techsupport@dmp.com.