HARDWARE UPDATE

1103 Universal Transmitter

March 2018

Hardware Update

All 1103 Universal Transmitters are now being manufactured and shipped with Level B hardware.

New Tamper Design

1103 Universal Transmitters now feature an updated on-board tamper button design. See Figure 1. The new design allows for additional travel by the tamper core prior to initiation of a tamper signal. This will allow the unit to be installed in more extreme field conditions and provide improved overall performance.



Figure 1: New 1103 Tamper Button

Obtaining the New Hardware

New 1103 Universal Transmitters can be ordered by contacting DMP Customer Service at 866-266-2826 or by visiting <u>Buy.DMP.com</u>.

