TECHNICAL UPDATE

Remote Link and System Link March 2012

Version 1.61 Software Update

Effective March 15, 2012, all Remote Link and System Link software is being manufactured as Version 1.61 (3/13/12). This version is an update from the Version 1.61 (2/15/2011) previously shipped and contains updated operation. If your current Remote Link or System Link software is previous to Version 1.46, update to Version 1.59 before updating to 1.61 (3/13/12).

Updated Operation

* * * IMPORTANT UPDATE INFORMATION * * *

Incorrect Database Update

Updating Remote Link to Version 1.61 (3/13/12) now updates the Remote Link database correctly.

Previously, updating the Remote Link database to Version 1.61 (2/15/12) could have resulted in corruption of panel programming in the database. Panels that were sent programming from a corrupted Remote Link database could be programmed incorrectly.

IMPORTANT NOTICE:

- 1. DMP STRONGLY RECOMMENDS THAT ALL REMOTE LINK INSTALLATIONS THAT WERE UPDATED TO VERSION 1.61 (2/15/12) BE UPDATED TO VERSION 1.61 (3/13/12).
- 2. THE REMOTE LINK DATABASE MUST THEN BE RESTORED FROM A BACKUP PREVIOUS TO 1.61 (2/15/12). REMOTE LINK WILL INDICATE A DATABASE OUT-OF-DATE, CHOOSE OKAY. REMOTE LINK WILL THEN FINISH THE UPDATE.
- 3. DMP ALSO RECOMMENDS RESENDING PANEL PROGRAMMING TO ANY AFFECTED PANELS AFTER APPLYING THIS UPDATE.

Obtaining the New Software

Remote Link and System Link Version 1.61 (3/13/12) updates are available for download free of charge on the DMP Dealer Direct Website at http://dmp.com/dealer.

