HARDWARE UPDATE

1100R Wireless Repeater

July 2010

Hardware Update

Effective July 2010, all 1100R Wireless Repeaters are being manufactured with Level C hardware.

Updated Hardware

Wall Tamper

The style of the wall tamper has been changed from a mechanical switch utilizing a spring to a carbon puck with a rubber switch mounted in the housing.

Additionally, a two-pin header has been added to allow the the wall tamper circuit to be enabled as required for specific applications. The wall tamper will ship from the factory disabled.

Power Supply

The barrel style DC power supply connection has been updated to a two-position terminal block. The new model 376L 12 VDC Plug-in power supply provides wire connections to the repeater and can be purchased separately.

Purchasing the New Hardware

The 1100R Level C hardware can be purchased at buy.dmp.com or by contacting Customer Service at 1-800-641-4282.

