## TECHNICAL UPDATE

# Remote Link and System Link August 2007

### Version 1.37 Software Update

Effective August 2007, all Remote Link and System Link software is being manufactured as version 1.37 (8/22/07). This version is an update from the Version 1.37 (8/10/07) previously shipped and contains updated operations.

## **Updated Operation**

### NAK'd Supervision Message

When Remote Link was used as host automation to monitor alarm signals from the SCS-1R receiver, a proper S99 (once a minute) supervision message from the receiver could have been NAK'd by Remote Link. This would cause Remote Link to incorrectly indicate the receiver was not communicating.

This situation only occurred if Remote Link and the SCS-1R receiver were configured to use any of the following:

- Line Numbers in messages
- Start Character
- CRC Error Checking
- Sequence Number

These options are configured in the Receiver tab of the Remote Link Configuration window and the Host Automation programming of the receiver. If Line# was set to 0 (zero) and the Start Character, CRC and Sequence Numbers were not used, the S99 messages were accepted by Remote Link and not NAK'd.

## **Obtaining the New Software**

Remote Link and System Link updates version 1.37 (8/22/07) are available for download free of charge on the DMP Dealer Direct Website at <a href="http://dmp.com/dealer">http://dmp.com/dealer</a>. Hard copy updates on CD can be obtained from buy.dmp.com or by calling DMP Customer Service at 1-800-641-4282.

